

Zana Kamangar

From: Zana Kamangar
Sent: Tuesday, August 30, 2022 1:54 PM
Subject: LEAD SEALS

During the MC Surveillance Audit, it is found out that some of the ITs are using a wrong type of **seals** and **plier dies**.

G Ihv=#

Each IT must have 3 Lead Dies:

- **NEE-A0023 die:** These lead seals can only be used when an official examination has been performed, by an IT.



- **NEE die:** This lead seal is for use while doing regular calibrations and repairs.



#


- **Blank die:** for the other side of the plier which goes with the above dies.



Ohdg#Vhdv=#

The only acceptable seal to use should be exactly size **3/8" (9.53 mm)**. The ASP number on the seal should be clear and complete.

Please check your seals some ITs have a smaller 1/4" (6.35mm) which is the wrong one, **if this is the case contact your supervisor immediately and replace it with the correct one.**



Kind Regards/Cordialement,

Zana Kamangar

Quality Systems Administrator

National Energy Equipment Inc.

1467 Spitfire Pl, Port Coquitlam, BC, V3C 6L4

Cell: 604-968-1921 | E-mail: zkamangar@nee.ca